

# CERTIFICATE OF COMPLIANCE

|                    |                   |
|--------------------|-------------------|
| Certificate Number | E230084           |
| Report Reference   | E230084-20060825  |
| Issue Date         | 2020-SEPTEMBER-10 |



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

Certificate Number E230084  
Report Reference E230084-20060825  
Issue Date 2020-SEPTEMBER-10

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

## Models

Component – Bridge Rectifiers, Package Code KBPC, Models KBPC, followed by 1, 6, 8, 10, 15, 25, 35 or 50, followed by 005, 01, 02, 04, 06, 08, 10; Package Code KBPC, Models BR, followed by 3, 6, 8, 10, 15, 25, 35 or 50, followed by 005, 01, 02, 04, 06, 08, 10;  
Package Code KBPC-W, Models KBPC, followed by 15, 25, 35 or 50, followed by 005, 01, 02, 04, 06, 08 or 10, followed by W;  
Package Code GBPC, Models GBPC, followed by 15, 25, 35 or 50, followed by 005, 01, 02, 04, 06, 08, 10 or 12;  
Package Code GBPC-W, Models GBPC, followed by 15, 25 or 35, followed by 005, 01, 02, 04, 06, 08, 10 or 12, followed by W;  
Package Code GBPC-W, Models GBPC, followed by 50, followed by 005, 01, 02, 04, 06, 08 or 10, followed by W



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

f UL. For questions, please

